## **BUILDING SAFETY CERTIFICATE**

No.

dated 26.04-2024

Is is certificate that the existing building SAN\_MARINO\_ACADEMY (Name of the building or premises) at JAGDISHSARAL CHANDAULI

------(address) is having blocks (s) as per details below:

Detail of blocks (s) in school	Block (1)	Block (2)	Block (3)	Block · (4)	Block (5)	Block (6)
No. of floor (s) in	G+1	1,0,0		73.		
the block						

The building is owned/occupied by <u>SAN MARINO ACADEMY</u> (name o the institution) have complied with safety requirement in accordance with national Building code Rules, and verified by the officers concerned of PROVINCIAL DIVISON: PUBLIC WORKS DEPARTMENT (Name of Department/Govt.) on 26-04-2024----(date of inspection) in the presence Of Boijesh Kumar, Chandaule (Name and addresses of Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 26,04.202 for period of----- S-years

Years in accordance with rule and subject to compliance of the specific condition as appended. •

Signature with Seal: प्रान्तीय खाउँ, ली Name: lashupati Nath Tseipathi

Designation: Asstt. Engineer

Name & Address of Department Office: P.W.D. Chandauli